



SALE PRE OWNED

**quicksilver Activ 875 sundeck**

**CAP Océan : 145 000 € All Tax Included**  
Marion +33(0) 7 71 91 77 82

**CAP Océan**  
Courtage Maritime

## Specifications

YEAR

2019

LENGTH

7.99

WIDTH

2.90

GUESTS CRUISING

12

CABINS

1

BATHROOMS

1

ENGINE MANUFACTURER

MERCURY

ENGINE HOURS

261

HORSE POWER

1 X 300 CV

## General

TYPE	BRAND	MODEL	GUESTS CRUISING
Motorboat	quicksilver	Activ 875 sundeck	12

## Dimensions / Performance

CRUISING SPEED (ND)	TOP SPEED (ND)
23	38

## Building / facilities

HULL MATERIAL	HULL COLOR	DECK MATERIAL	AMOUNT OF CABINS
POLYESTER	WHITE AND BLACK	teak	1
BERTHS	BATHROOM(S)		
4	1		

## Building / facilities description

Convertible saloon Air conditioning Water Heaters Marine toilet

## Engine room

ENGINE	NUMBER OF ENGINES HORSE POWER (CV)	ENGINE HOURS	PROPULSION
MERCURY	1 x 300	261	TRIPALES
PROPELLERS	FUEL	BOW THRUSTER	
Hors-Bord	gasoline		

## Electricity / air conditioning

---

ENGINE BATTERY

BATTERY  
CHARGER

AIR CONDITIONING

## Electricity / air conditioning description

---

Shore power Electrical system 220 V Electrical system 12 V Charger Alternator Service batteries 3 Engine batteries Inverter VICTRON

## Navigation equipment

---

GPS

NAVIGATION COMPASS

SONAR

SPEEDOMETER

ANCHOR

## Navigation equipment description

---

Log-speedometer

Compass

GPS

Chart

Sounder

Central navigation SIMRAD

Navigation software

## Galley / Laundry / Entertainment

---

FRIDGE

### **Galley description**

---

Refrigerator

Hob GAZ

### **Entertainment description**

---

Radio-CD FUSION

### **Deck equipment**

---

BIMINI

### **Deck equipment description**

---

Gangway

Cockpit teak

Teak deck

Swimming platform

Swimming ladder

Cockpit shower

Cockpit table

Cockpit lighting

Barbecue

Foredeck suncushion

Cockpit sun bed

Cockpit cushions

Bimini top

Camping awning

## **Safety equipment / miscellaneous**

---

BILGE PUMP

## **Boat equipment description**

---

Bow thruster

Trim tabs Electriques

Anchor

Electric Windlass

Bilge Pump

Safety equipment côtier

Antifouling











