





Description

Second owner.

Maintenance work carried out by the current owner:

2022) disassembly of propellers sterndrives - Left sterndrive: oil drain, disassembly of propeller shafts - Small turned propeller shaft for thread machining of the ogive locking bolt. Replace all seals and bearings.

2023) replaced right trim sensor - assembly of new propellers and nosepieces - replacement of the upper gasket kit of the two toilets - replaced all service and engine batteries.

2024) replaced the windlass again.

Navigation equipment:

Rudder angle indicator, Log (Raymarine), Chartplotter (Raymarine).

Staging and technical:

Engine Alarm, Bilge Alarm, Water pressure pump, 3 Batteries (Bosh 180 AH - Exide 105 AH - Varta 190 AH), Deck Shower, Directional Spotlight, Electric Flaps, Courtesy Lights, Gangway (idraulica), Manual Bilge Pump, Teak Cockpit, Shorepower connector, Water harbor connector system, Rollbar, Electric Windlass, swimming ladder, cockpit table, Horn.

Domestic Facilities onboard:

Warm Water System, 12V Outlets, 220V Outlets, Black Water Tank, 2 Electric Toilet.

Specifications

YEAR

2008

WIDTH

4.03

GUESTS CRUISING

10

BATHROOMS

1

HORSE POWER

2 X 330 CV

LENGTH

12.04

FUEL TANK CAPACITY

850

CABINS

2

ENGINE MANUFACTURER

Volvo Penta D6-330



Ge	n		ra
96		G	·

TYPE BRAND MODEL GUESTS CRUISING

Motorboat azimut Atlantis 42 ht 10

Dimensions / Performance

FUEL CAPACITY (L) 850

Building / facilities

AMOUNT OF CABINS BERTHS BATHROOM(S)

2 4

Engine room

ENGINE NUMBER OF ENGINES HORSE POWER (CV) FUEL BOW THRUSTER

Volvo Penta D6-330 2 x 330 Diesel

Electricity / air conditioning

ENGINE BATTERY
BATTERY
CHARGER





Navigation equipm	ıent
-------------------	------

TRACER AUTO PILOT VHF NAVIGATION COMPASS

SONAR SPEEDOMETER ANCHOR

Galley / Laundry / Entertainment

OVEN MICROWAVE FRIDGE TV

Deck equipment

DECK SHOWER CANOPY

Safety equipment / miscellaneous

BILGE PUMP



































































