





Description

VERY GOOD OVERALL CONDITION

ATTENTIVE AND SCRUPULOUS OWNER

CONSTANTLY PERFORMED MAINTENANCE

LIST OF MECHANICAL AND AESTHETIC WORK CARRIED OUT BETWEEN 2021 AND 2023 AVAILABLE ON REQUEST (DEMONSTRABLE WITH INVOICES)

CARD BEING UPDATED

Ref. M

Navigation equipment:

Rudder angle indicator, Plotter with GPS antenna.

Staging and technical:

Engine Alarm, Bilge Alarm, Water pressure pump, Special Colour (SCAFO ROSSO), Deck Shower, Directional Spotlight, Electric Flaps, Anchor Chain Washdown, Washbasin in the cockpit, Courtesy Lights, Gangway, Platform, Automatic Bilge Pump, Manual Bilge Pump, Entry door, Shorepower connector, Voltage Rectifier, Rollbar, Electric Windlass, swimming ladder, cockpit table, Horn.

Domestic Facilities onboard:

Warm Water System, 12V Outlets, 220V Outlets, Electric Toilet.

Entertainment:

Specifications

YEAR

1989

WIDTH

4.19

FUEL TANK CAPACITY

2000

CABINS

2

ENGINE MANUFACTURER

MAN

HORSE POWER

2 X 820 CV

LENGTH

15.14

DRAFT

1.00

GUESTS CRUISING

10

BATHROOMS

L

ENGINE HOURS

280



•	 _	

TYPE BRAND MODEL GUESTS CRUISING

Motorboat riva 51 turborosso 10

CURRENT LOCATION

Mar ligure

Dimensions / Performance

 WEIGHT (T)
 FUEL CAPACITY (L)
 CRUISING SPEED (ND)
 TOP SPEED (ND)

 9999.99
 2000
 32
 36

Building / facilities

HULL MATERIAL AMOUNT OF CABINS BERTHS BATHROOM(S)

Vetroresina 2 4 1

Engine room

ENGINE NUMBER OF ENGINES HORSE POWER (CV) ENGINE HOURS FUEL

MAN 2 x 820 280 Diesel

Electricity / air conditioning

ENGINE BATTERY BATTERY GENERATOR CHARGER



Nav	igati	ion (equi	pment
-----	-------	-------	------	-------

GPS VHF NAVIGATION COMPASS SONAR

SPEEDOMETER ANCHOR

Galley/Laundry/Entertainment

FRIDGE TV

Deck equipment

BIMINI

Safety equipment / miscellaneous

BILGE PUMP





































































