





Description

The Birchwood TS37, built in 1985 and located in Penton hook Marina, UK, is a spacious cruiser ideal for living aboard or extended cruising. This vessel is 11.28 metres in length with a 3.78 metres beam and is powered by twin Volvo Penta TAMD40B diesel engines with incredibly low hours from new. She has benefited from a full refit inside with a considerable amount of upgrades. She features a comfortable aft cabin, a separate dinette area, diesel heating, a holding tank for the forward toilet, and a recent set of new canopy's including windscreen covers and fly screens. Additional amenities include an upgraded light install, marine head, refrigerator, new hob and oven, full re-trimmed sofa and dinette seating, bow and stern thruster. The list goes on, thousands spent!! The Boat Safety Certificate is current and valid. With her recent refit makes this particular boat a step above the rest and still at great value. Her current mooring is available and in a beautiful spot with a lovely community and social life. Disclaimer The Company offers the details of this vessel in good faith but cannot guarantee or warrant the accuracy of this information nor warrant the condition of the vessel. A buyer should instruct his agents, or his surveyors, to investigate such details as the buyer desires validated. This vessel is offered subject to prior sale, price change, or withdrawal without notice. Disclaimer The Company offers the details of this vessel in good faith but cannot guarantee or warrant the accuracy of this information nor warrant the condition of the vessel. A buyer should instruct his agents, or his surveyors, to investigate such details as the buyer desires validated. This vessel is offered subject to prior sale, price change, or withdrawal without notice.

Specifications

	· · · · · · · · · · · · · · · · · · ·
YEAR	LENGTH
1985	11.94
WIDTH	CABINS
3.79	2

BATHROOMS

2



General			
BRAND	MODEL	CURRENT LOCATION	
birchwood	Boats ts37	Chertsey united kingdom	
Ruilding / facilities			
Building / facilities			
Building / facilities	AMOUNT OF CABINS	bathroom(s)	

Engine room

NUMBER OF ENGINES (CV)























































